


**Notes**

① COVER SPLICES WITH SHRINK TUBE

② HGM CAN BUSS SHOULD BE FLUSHED TO THE MAIN BODY OF HARNESS (USE MASTER FOR REFERENCE)

Coverings	
Id	Assembly
[17]	

Revisions			
Rev.	Date	Author	Description
A	6/9/2021	Ulysses Aguirre	



From	To	Conductor	Notes
HOLLEY_ECU.1	HOLLEY_LCD.1	W7.Red	+12V Power
HOLLEY_ECU.2	S1	W2.Tan-Black	CAN High
HOLLEY_ECU.3	S2	W1.Tan	CAN Low
HOLLEY_ECU.4	HOLLEY_LCD.4	W8.Black	Ground

From	To	Conductor	Notes
HOLLEY_LCD.1	HOLLEY_ECU.1	W7.Red	+12V Power
HOLLEY_LCD.2	S1	W6.Tan-Black	CAN High
HOLLEY_LCD.3	S2	W5.Tan	CAN Low
HOLLEY_LCD.4	HOLLEY_ECU.4	W8.Black	Ground

From	To	Conductor	Notes
HGM_CAN_BUS.1	S1	W4.Tan-Black	CAN High
HGM_CAN_BUS.2	S2	W3.Tan	CAN Low

Title	----	Part Number	50101	
Description	HOLLEY EFI "Y" CONNECTOR		Revision	----

	Name	Date
Drawn By	UA	6/9/2021
Eng Approved	----	----
Mfg Approved	----	----
QA	----	----



This document contains confidential and proprietary information that cannot be reproduced or divulged, in whole or in part, without written authorization.